



Dolan Chemical Laboratory
4001 Bixby Road
Groveport, OH 43125
T: 614-836-4221, Audinet 210-4221
F: 614-836-4168, Audinet 210-4168
<http://aepenv/labs>

Water Analysis

Location: Mountaineer Plant

Report Date: 10/2/2013

1st Stage Feed

Sample Number: 133896-001 **Date Collected: 09/25/2013 08:00** **Date Received: 9/25/2013**

Parameter	Result	Units	Data Qual	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se	310	ug/L		0.50	0.20	DPC	10/01/2013	EPA 200.8

2nd Stage Feed

Sample Number: 133896-002 **Date Collected: 09/25/2013 08:00** **Date Received: 9/25/2013**

Parameter	Result	Units	Data Qual	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se	28.9	ug/L		0.50	0.20	DPC	10/01/2013	EPA 200.8

Bioreactor Effluent

Sample Number: 133896-003 **Date Collected: 09/25/2013 08:00** **Date Received: 9/25/2013**

Parameter	Result	Units	Data Qual	RL	MDL	Analysis By	Analysis Date/Time	Method
Selenium, Se	1.7	ug/L		0.50	0.20	DPC	10/01/2013	EPA 200.8

U: Analyte was analyzed and not detected at or above adjusted Method Detection Limit

J: Analyte was positively identified, though the quantitation was below Reporting Limit.

Brian Snyder, Chemist II

Email bssnyder@aep.com

Fax 614-836-4168

Tel. 614-836-4224

Audinet 210-4224

THIS TEST REPORT RELATES ONLY TO THE ITEMS TESTED AND SHALL NOT BE REPRODUCED EXCEPT IN FULL WITHOUT WRITTEN APPROVAL OF THE LABORATORY. ALL TEST RESULTS MEET ALL OF THE REQUIREMENTS OF THE ACCREDITING AUTHORITY, UNLESS OTHERWISE NOTED.